## Mey to Photographs

PA Upper Swedish Log Cabin 23 - Darb.v Near Darby, Phila., Pa.

- 1 View Grom northwest. February 5, 1937. Photo by Tan McLaughlin.
- 2 Exterior, general view of rear and end, from west. Sept. 12, 1940. Photo by Stanly P. Mixon.
- 3 Exterior, detail view of north elevation, from north-east, showing joint of addition. Sept. 12, 1940. Unxon.
- 4 Exterior, detail south elevation, showing jointing of logs on later extension. Sept. 12, 1940.

  Hixon.